

**PCN: V16-006-E47540-0A**

## Product Change Notice

Issue Date: 09 JUN 2016

**Change Type:**

Add a receptacle vendor for 10G Box TOSAs

**Parts Affected:**

1625L, 1626L, 1655L and 1656L type 10G box TOSAs

**Description and Extent of Change:**

Adding a new receptacle supplier to the Broadcom supply chain

**Reasons for Change:**

Increase supply chain robustness

**Effect of Change on Fit, Form, Function, Quality, or Reliability:**

There is no change to the fit, form, function or reliability of the device.

**Effective Date of Change:**

Product shipments with this change could begin as early as 90 days after the issue date of this Product Change Notice.

**Recommended Actions to be Taken by Customer:**

No action required. PCN is for information only.

**Qualification Data:**

Qualification data is available upon request.

---

These changes have been reviewed and approved by Broadcom Limited engineers and managers per Broadcom Limited procedure: Change Control and Customer Notification, 5962-6052-80.

Please contact your Broadcom Limited field sales for any questions or support requirements. Please return any response as soon as possible, but not to exceed 30 days.