

Global Change Notification (GCN)

| | | |
|--|--|-----------------|
| Product Family | 0.5 IO/1.25 · 2.0 FLOATING/1.25WTB/2.0 PLUG COVER B/MSE HA CANAL BA-D TYPE-01 HARNESS/PANEL MOUNT PLUG COVER ASET/SMALL-MGC PCB MOUNT REC | 10705533 |
| | | GCN Number |
| Series | 55949/53780/55959/55763/51339/52968/52969/53717/ | August 13, 2015 |
| | | Date Issued |
| Reason For Change | Tooling / Equipment Transfer | |
| Change Description | <p>This is to inform you of a transfer plan for molding dies of the following series. 55949/53780/55959/55763/51339/52968/52969/53717/53718/54702/54798/55533/55790/55085/503930/55084 series. As the current supplier of the molding process will go out of business, Molex will shift to other suppliers and Molex Japan plant to keep molding production. There will be no influences on product's fit, form, function, nor manufacturing method. Also, the current final assembly sites do not change. Molex will surely implement a quality test to avoid any quality issues. The manufacturing activity in new sites is scheduled to start around 15th August 2015 (This schedule will vary by each product, and might be changeable due to Molex's transfer arrangements and demand from our customers). The affected Finished Products are as follows ·</p> <ul style="list-style-type: none"> · · 559492639, 547980461, 557901461, 559492619, 529690661, 529691261, 537180619, 537181219, 513390669, 547021219, 555331219, 537170619, 537170819, 529680819, 557633072, 557634070, 557632070, 557633070, 559592630, 559592631, 559592830, 537808603, 550851805, 5039300110, 5039300111, 5039300211, 550841825 | |
| | | |
| Part Numbers Affected | Please refer to CustomerPartList.csv attached to e-mail message. | |
| Reason For Short Notice Exception | Force Majeure | |
| Assessment Of Change (How Product Will Be Qualified & Validated) | There will be no influences on product's fit, form, function, nor manufacturing method. Also, the current final assembly sites do not change. Molex will surely implement a quality test to avoid any quality issues. | |
| Internal Molex Qualification Date (Planned Date Information Available) | August 07, 2015 | |
| Sample Availability Date (Changed Part) | August 11, 2015 | |
| Date of Implementation | August 14, 2015 | |
| Method of Identifying Change | Lot NO. | |
| Recommended Replacement Parts | Not Applicable | |
| Last Time Buy Date for Obsolete Parts | | |
| Last Time Ship Date for Obsolete Parts | | |

| Contact | Name | E-mail | Phone Number |
|---|---|----------------------------|-----------------|
| Sales Engineer | Please refer to e-mail message for your local sales engineer. | | |
| Regional Coordinator (Japan and Korea) | Naomi Maruyama | Naomi.Maruyama@molex.co.jp | +81-46-265-2416 |
| Regional Coordinator (Asia- excluding Japan and Korea) | Allen Yu | Allen.Yu@molex.com | +886-2-66251751 |
| Regional Coordinator (Europe, Middle East, Africa) | Agnes Mburu | Agnes.Mburu@molex.com | +31-40-295-8271 |
| Regional Coordinator (Americas) | Maria Sullivan | Maria.Sullivan@molex.com | 1-727-322-4352 |

Molex, Inc.
 2222 Wellington Court
 Lisle, IL 60532
 TEL: 630-969-4747
www.molex.com