

PCN Notice

Additional connector assembly equipment will be added for production of part numbers MX34R20VF1 and MX34R32VF1. There will also be an additional insulator molding die added for part number MX34R20VF1. All new tooling and equipment will be duplicates of existing production equipment. There will be no change in form, fit or function.

1. Part Numbers Affected:

New Assembly Equipment:

MX34R20VF1

MX34R32VF1

New mold die:

MX34R20VF1

For existing customers who require any special documentation such as PPAP, please contact your JAE account representative by March 29, 2019.

If you have any questions regarding this matter, please contact your JAE account manager.

Thank you for your cooperation.

