



Eaton
Electronics Division
5735 W. Las Positas Blvd #100
Pleasanton, CA 94588
www.eaton.com/electronics

Product Change Notice

PCN#: EE-PCN18032

8/20/2018

CLASSIFICATION OF CHANGE:

Manufacture location

DESCRIPTION OF CHANGE:

A new Taiwan manufacture location will be added for various fuse holders.

REASON FOR CHANGE:

Enhance the capability for the future growth.

EXPECTED INFLUENCE ON QUALITY, RELIABILITY, AND PERFORMANCE:

There will be no effect on the quality, reliability, or performance. There are no changes to form, fit, and function of the devices.

PARTS FAMILIES AFFECTED

See attached for detailed part numbers.

TIME SCHEDULE:

Effective immediately

ISSUED BY:

Wayne Wang
Product Manager – Circuit Protection

CONTACT INFORMATION:

For questions or comments, please contact your local [Eaton sales representative](#).

Eaton Family	Eaton Part Number
HR/HM/HH	BK-9838
HR/HM/HH	BK-9841
HR/HM/HH	BK-1A1853
HR/HM/HH	BK-HHJ-1K0118
HR/HM/HH	BK-HHJ-A-R
HR/HM/HH	BK-HHJ-B-R
HR/HM/HH	BK-HHJ-C-R
HR/HM/HH	BK-HME
HR/HM/HH	BK-HMF
HR/HM/HH	BK-HMG
HR/HM/HH	BK-HMH
HR/HM/HH	BK-HMI
HR/HM/HH	BK-HMJ
HR/HM/HH	BK-HMK
HR/HM/HH	BK-HRE
HR/HM/HH	BK-HRG
HR/HM/HH	BK-HRI
HR/HM/HH	BK-HRJ
HR/HM/HH	BK-HRK-R
HR/HM/HH	HHJ-A-R
HR/HM/HH	HME
HR/HM/HH	HMF
HR/HM/HH	HMG
HR/HM/HH	HMH
HR/HM/HH	HMI
HR/HM/HH	HMJ
HR/HM/HH	HMJ-LESS-FUSE
HR/HM/HH	HMK
HR/HM/HH	HRE
HR/HM/HH	HRF
HR/HM/HH	HRG
HR/HM/HH	HRH
HR/HM/HH	HRI
HR/HM/HH	HRJ
HR/HM/HH	HRJ-LESS-FUSE
HR/HM/HH	HRK-R

Eaton Family	Eaton Part Number
HFB	BK-HFB-R
HFB	BK-HFB-10
HFB	HFB-R
HFB	HFB-10
HFB	BK1-HFB-R
HFB	BK1-HFB-10
HFB	BK-1A2294
HFB	BK-1A2294-01
HHB	BK-HHB-R
HHB	HHB-1K0187
HHB	BK-HHB-Y408
HHB	BK-HHB-B408
HHB	BK-HHB-Y419
HHB	HHB-R
HHB	BK-HHB-B419
HHB	BK-HHB-RED
HHB	BK-HHB-R419
HHB	BK-HHB-R408