



## Global Change Notification (GCN)

Product Family	Impact 2PR BP Header	10675647
		GCN Number
Series	Multiple	March 20, 2015
		Date Issued
Reason For Change	Change In Packaging Specifications	
Change Description	<p>This letter is to inform you of a packaging change on guided Impact 100 Ohm 2 Pair backplane headers. The finger hole size in the base of the tray is being reduced to prevent parts at the end of the pocket row from sliding out of pocket into the finger hole, which in turn damaged the tails during shipping and handling. This is not an issue for unguided headers. There is no changes to the SPQ or MOQ due to this change. Qualification Test will be conducted to qualified the new packaging.</p>	



Part Numbers Affected	Please refer to CustomerPartList.csv attached to e-mail message.
Reason For Short Notice Exception	8D Corrective Action Changes
Assessment Of Change (How Product Will Be Qualified & Validated)	Qualification test
Internal Molex Qualification Date (Planned Date Information Available)	February 24, 2015
Sample Availability Date (Changed Part)	February 24, 2015
Date of Implementation	March 30, 2015
Method of Identifying Change	TBC
Recommended Replacement Parts	NA
Last Time Buy Date for Obsolete Parts	
Last Time Ship Date for Obsolete Parts	

Contact	Name	E-mail	Phone Number
Sales Engineer	Please refer to e-mail message for your local sales engineer.		
Regional Coordinator (Japan and Korea)	Naomi Maruyama	Naomi.Maruyama@molex.co.jp	+81-46-265-2416
Regional Coordinator (Asia- excluding Japan and Korea)	Allen Yu	Allen.Yu@molex.com	+886-2-66251751
Regional Coordinator (Europe, Middle East, Africa)	Agnes Mburu	Agnes.Mburu@molex.com	+31-40-295-8271
Regional Coordinator (Americas)	Maria Sullivan	Maria.Sullivan@molex.com	1-727-322-4352

**Molex, Inc.**  
 2222 Wellington Court  
 Lisle, IL 60532  
 TEL: 630-969-4747  
[www.molex.com](http://www.molex.com)