

<b>Product Name:</b>	HPL - 560 / 588	
	MILLIPACS	
<b>Product Manager:</b>	Pranith Joy	
<b>Subject:</b>	Notification of Planned Change	
<b>Distribution:</b>	Affected customers	
<b>Type of Change:</b>	Packaging Change	
<b>Change Description:</b>	<p>Carrier Tape Packing Reel design change &amp; colour change</p> <div style="display: flex; justify-content: space-around;"> <div style="text-align: center;"> <p><b>Before Change</b></p> <p><b>Existing Bobbin</b> 2 parts (Flange 1 + Flange 2) Black Color</p>  </div> <div style="text-align: center;"> <p><b>After Change</b></p> <p><b>New Bobbin</b> 3 parts (Flange 1 + Extender + Flange 2) Blue Color</p>  </div> </div> <p><small>Description of Change. &gt; Carrier Tape Packing Reel design change &amp; colour change</small></p>	
<b>Reason for Change:</b>	Alternate supplier introduction for supply continuity. We will have the flexibility to choose colours "White, Black, Blue etc for Bobbins as available in the resin market due to disrupted supply chain.	
<b>Affected Parts:</b>	See Affected parts.xls	
<b>Effective Date of Change:</b>	30 June ,2022	
<b>Last Time Buy Date:</b>		
<b>Earliest Disty Return Date:</b>		
<b>Last Time Shipment Date</b>		
<b>Datasheet Attached?</b>	NA	
<b>Qual/Test Data Attached?</b>	NA	
<b>Samples Availability Date:</b>	28 June ,2022	
<b>Available Alternatives?</b>		
<b>Questions?</b>	<i>Contact your local Amphenol Representative, or Product Manager</i>	
	<i>Product Manager</i>	
	<a href="mailto:PRANITH.JOY@FCI.COM">PRANITH.JOY@FCI.COM</a>	

**Note:**

Customers should contact Product Manager (or their local Amphenol Representative) directly regarding any concern on the PCN. Lack of any such customer feedback within three weeks of PCN release date will be interpreted as non-objection .

**MPN**

- 10120045-200LF
- 10120045-201LF
- 10120045-400LF
- 10120045-401LF
- 10158470-102LF
- HM2P09SZ5110N9LF
- HM2P09SZ5111N9LF
- HM2P11SZ5001N9LF
- HM2P11SZ5011N9LF
- HM2P40SZ5110N9LF
- HM2P40SZE121N9LF