Product Discontinuation



PD_331_20 **!! UPDATE !!**

Updated Information in BLUE TYPE

Last Order Date: 2021-05-31
Last Delivery Date: 2021-11-30

Reason: Products have reached end of life

Original: Product Discontinuation N° 331/20 dated 2020-11-30 Update: FS200R07A5E3_S6 (SP001150884) revoked

| DISCONTINUED | | | | NEW (REPLACEMENT) | | | |
|------------------|------------------------|----------------------|--------------|-------------------|------------------------|----------------------|--------------|
| Sales Name | SP Number | OPN | Package | Sales Name | SP Number | OPN | Package |
| FS200R07A5E3_S6 | SP001150884 | FS200R07A5E3S6BPSA1 | AG-HYBRIDL-1 | FS200R07A02E3_S6 | SP001661220 | FS200R07A02E3S6BKSA2 | PG-MDIP-28 |
| FS900R08A2P2_B31 | SP001232072 | FS900R08A2P2B31BOSA1 | AG-HYBRID2-1 | FS950R08A6P2B | SP001720776 | FS950R08A6P2BBPSA1 | AG-HYBRIDD-1 |
| FS900R08A2P2_B32 | SP001709602 | FS900R08A2P2B32BOSA1 | AG-HYBRID2-1 | FS950R08A6P2B | SP001720776 | FS950R08A6P2BBPSA1 | AG-HYBRIDD-1 |

If you have any questions, please do not hesitate to contact your local sales office.

Disclaimer: The supply of this product will stop after the date of last delivery as outlined herein. Final orders can only be accepted on or before the last order date and are subject to the availability. Early ordering is strongly recommended! If Infineon confirms a purchase order with a delivery date beyond last delivery date, the PD with the mentioned last ordering date still remains valid.

2021-06-01