



CUSTOMER OPERATIONS
160 RIO ROBLES
SAN JOSE, CA 95134

PDN #: M000989N

DATE: 11-Apr-2020

PRODUCT DISCONTINUANCE NOTICE

Notice Type	Maxim Part Number	Recommended Replacement	Last Order Date	Last Delivery Date	Reason
Discontinuance	806-0505-30+	N/A	11-Apr-2020	11-Apr-2020	Part can no longer be manufactured
Discontinuance	806-0505-30+T	N/A	11-Apr-2020	11-Apr-2020	Part can no longer be manufactured
Discontinuance	806-0539-22+D	N/A	06-Apr-2021	03-Oct-2021	Part can no longer be manufactured
Discontinuance	MAX14675EETE+	N/A	11-Apr-2020	11-Apr-2020	Part can no longer be manufactured
Discontinuance	MAX14675EETE+T	N/A	11-Apr-2020	11-Apr-2020	Part can no longer be manufactured
Discontinuance	MAX14830ETM+CPA	N/A	11-Apr-2020	11-Apr-2020	Part can no longer be manufactured
Discontinuance	MAX14830ETM+TCPA	N/A	11-Apr-2020	11-Apr-2020	Part can no longer be manufactured
Discontinuance	MAX2550ETN+G2Z	N/A	11-Apr-2020	11-Apr-2020	Part can no longer be manufactured
Discontinuance	MAX2550ETN+TG2Z	N/A	11-Apr-2020	11-Apr-2020	Part can no longer be manufactured
Discontinuance	MAX3488AEASA+	N/A	11-Apr-2020	11-Apr-2020	Part can no longer be manufactured
Discontinuance	MAX3488AEASA+T	N/A	11-Apr-2020	11-Apr-2020	Part can no longer be manufactured
Discontinuance	MAX3490AEASA+	N/A	11-Apr-2020	11-Apr-2020	Part can no longer be manufactured
Discontinuance	MAX3490AEASA+T	N/A	11-Apr-2020	11-Apr-2020	Part can no longer be manufactured
Discontinuance	MAX3802UTK+	N/A	11-Apr-2020	11-Apr-2020	Part can no longer be manufactured
Discontinuance	MAX385CSE+T	N/A	11-Apr-2020	11-Apr-2020	Part can no longer be manufactured
Discontinuance	MAX5861TEXA+WCKQ	N/A	11-Apr-2020	11-Apr-2020	Part can no longer be manufactured
Discontinuance	MAX6072BAUB25+	N/A	11-Apr-2020	11-Apr-2020	Part can no longer be manufactured
Discontinuance	MAX6072BAUB41+	N/A	11-Apr-2020	11-Apr-2020	Part can no longer be manufactured
Discontinuance	MAX6072BAUB41+T	N/A	11-Apr-2020	11-Apr-2020	Part can no longer be manufactured
Discontinuance	MAX6072BAUB50+T	N/A	11-Apr-2020	11-Apr-2020	Part can no longer be manufactured
Discontinuance	MAX77621EWI+	N/A	11-Apr-2020	11-Apr-2020	Part can no longer be manufactured
Discontinuance	MAX77621EWI+T	N/A	11-Apr-2020	11-Apr-2020	Part can no longer be manufactured
Discontinuance	MAX9979KCTK+TDW	N/A	11-Apr-2020	11-Apr-2020	Part can no longer be manufactured
Discontinuance	MAXQ610A-2524+T	N/A	11-Apr-2020	11-Apr-2020	Part can no longer be manufactured
Discontinuance	MAXQ610A-2533+T	N/A	11-Apr-2020	11-Apr-2020	Part can no longer be manufactured
Discontinuance	MAXQ610A-2535+T	N/A	11-Apr-2020	11-Apr-2020	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 12-May-2020

Discontinuance	MAXQ610X-2047+	N/A	11-Apr-2020	11-Apr-2020	Part can no longer be manufactured
Discontinuance	MAXQ610X-2048+	N/A	11-Apr-2020	11-Apr-2020	Part can no longer be manufactured
Discontinuance	MAXQ610X-2049+	N/A	11-Apr-2020	11-Apr-2020	Part can no longer be manufactured
Discontinuance	MAXQ610X-2050+	N/A	11-Apr-2020	11-Apr-2020	Part can no longer be manufactured
Discontinuance	MAXQ610X-2507+	N/A	11-Apr-2020	11-Apr-2020	Part can no longer be manufactured
Discontinuance	MAXQ610X-2526+	N/A	11-Apr-2020	11-Apr-2020	Part can no longer be manufactured
Discontinuance	MAXQ610X-2551+	N/A	11-Apr-2020	11-Apr-2020	Part can no longer be manufactured
Discontinuance	MAXQ610X-2558+	N/A	11-Apr-2020	11-Apr-2020	Part can no longer be manufactured
Discontinuance	MAXQ610X-2559+	N/A	11-Apr-2020	11-Apr-2020	Part can no longer be manufactured
Discontinuance	MAXQ610X-2561+	N/A	11-Apr-2020	11-Apr-2020	Part can no longer be manufactured
Discontinuance	MAXQ610X-2564+	N/A	11-Apr-2020	11-Apr-2020	Part can no longer be manufactured
Discontinuance	MAXQ610X-2565+	N/A	11-Apr-2020	11-Apr-2020	Part can no longer be manufactured
Discontinuance	MAXQ610X-2594+	N/A	11-Apr-2020	11-Apr-2020	Part can no longer be manufactured
Discontinuance	MAXQ610X-2597+	N/A	11-Apr-2020	11-Apr-2020	Part can no longer be manufactured
Discontinuance	MAXQ610X-2601+	N/A	11-Apr-2020	11-Apr-2020	Part can no longer be manufactured
Discontinuance	MAXQ612X-2049+	N/A	11-Apr-2020	11-Apr-2020	Part can no longer be manufactured
Discontinuance	MAXQ613J-UEI+	N/A	11-Apr-2020	11-Apr-2020	Part can no longer be manufactured
Discontinuance	MAXQ618X-2574+	N/A	11-Apr-2020	11-Apr-2020	Part can no longer be manufactured
Discontinuance	MAXQ622G-UEI+	N/A	11-Apr-2020	11-Apr-2020	Part can no longer be manufactured
Discontinuance	MAXQ636V-2614+T	N/A	06-Apr-2021	03-Oct-2021	Part can no longer be manufactured
Discontinuance	PHY1090-DS-FR	N/A	11-Apr-2020	11-Apr-2020	Part can no longer be manufactured