



Product Change Notification - SYST-14LUPH761

Date:

16 Apr 2020

Product Category:

Clock and Timing - Clock and Data Distribution

Affected CPNs:



Notification subject:

Data Sheet - PL102-10 - Low Skew Output Buffer Datasheet Document Revision

Notification text:

SYST-14LUPH761

Microchip has released a new Product Documents for the PL102-10 - Low Skew Output Buffer of devices. If you are using one of these devices please read the document located at [PL102-10 - Low Skew Output Buffer](#).

Notification Status: Final

Description of Change: 1) Converted Micrel document PL102-10 to Microchip data sheet template DS20006345A. 2) Minor text changes throughout.

Impacts to Data Sheet: None

Reason for Change: To Improve Productivity

Change Implementation Status: Complete

Date Document Changes Effective: 16 April 2020

NOTE: Please be advised that this is a change to the document only the product has not been changed.

Markings to Distinguish Revised from Unrevised Devices: N/A

Attachment(s):

[PL102-10 - Low Skew Output Buffer](#)

Please contact your local [Microchip sales office](#) with questions or concerns regarding this notification.

Terms and Conditions:

If you wish to [receive Microchip PCNs via email](#) please register for our PCN email service at our [PCN home page](#) select register then fill in the required fields. You will find instructions about registering for Microchips PCN email service in the [PCN FAQ](#) section.

If you wish to [change your PCN profile, including opt out](#), please go to the [PCN home page](#) select login and sign into your myMicrochip account. Select a profile option from the left navigation bar and make the applicable selections.

Affected Catalog Part Numbers (CPN)

PL102-10SC-R

PL102-10TC

PL102-10TC-R