BOURNS

Product Obsolescence Memo

TRANSFORMERS



January, 2015

Bourns® Model PM61300 Series SMD CCFL Transformer to be Discontinued

Bourns will be discontinuing the Bourns[®] Model PM61300 Series SMD CCFL Transformer. A lack of sales volume and diminishing demand necessitates this action. Regrettably, no replacement part numbers are available at this time.

Obsolete Part Numbers
PM61300-1-RC
PM61300-2-RC
PM61300-3-RC
PM61300-4-RC
PM61300-5-RC

Please plan for the following deadlines:

Last time buy date: July 20, 2015 Last time ship date: January 16, 2016

Should you have any questions or need additional information, please feel free to contact Customer Service/Inside Sales.