

Document Receipt Acknowledgement
Date:
Section:
Name:



Date

Attention:

DIGI-KEY/THIEF RIVER FALLS/MN/HQ

4M Change Notice

WIT2450FG and WIT2450M2

Dear. Valued Customer

Thank you very much for your great and continued support for business with Murata. This is the official notification that some of our products' 4M Change will be proceeded as detailed below. Please review this, and confirm that you will expect to receive products after this 4M Change. Your understanding and support are highly appreciated.

1. Product Type, Changes, and Customer/Murata/Alternative Part Numbers:

Product Type: WIT2450FG and WIT2450M2

Changes: Man Machine Material Method

Before Change	After Change
WIT2450FG Rev W	WIT2450FG Rev X
WIT2450M2 Rev AD	WIT2450M2 Rev AE
Items of Change:	
1. Seam solder shield	
2. Updated driver amp circuit	
3. Updated firmware to control new amp	

Please refer to the attached documents for detailed Part Numbers' information.

2. Reasons/Background:

Updated driver amp because of EOL
Seam solder shield to pass regulatory bodies

3. Products Before and After the Change:

There are no changes of the products' design, quality, guaranteed specifications, and other as Murata continuously uses the same production process and quality control system.

4. Change Schedule:

Production with change: 06. 15, 2018
Last Production Date without change: 01. 01, 2018
Last Shipment Date without change: 01. 01, 2018
Please note all EOL orders received will be implemented with the change

5. Contact Window:

Should you have any questions or concerns, please contact Murata Sales, Representative, or Distributor in your area.

Truly Yours. Thank you.

Murata Manufacturing, Co., Ltd.

IoT Module Products Dept./Senior Manager, Marketing
Jim Philipp



CS

EON020180501

May. 30, 2018

low.

ers,